## Approved For Release 2003/02/27 : CIA-RDP61-00763A000100090058-2

080-2605-59 Copy & of 6

20 April 1959

MEMORANIAM FOR: Acting Chief, UPD

SUBJECT

: Malfunction Report, Period Ending 31 March 1959

1. The following malfunction information is presented for the period ending 31 March 1959:

### I. Air Frame and Enginee

- A. Article 355 Experienced fuel venting for thirtyfive minutes 3 March. This is a recurring problem and IAC advises that the vent mod now in progress will eliminate.
- B. Article 367 Encountered a defective altimeter or leak in pilot-static system 3 March. Corrected locally.

#### II. Communications

A. Detachment B - No equipment failures for March

B.

C. Detachment D - One recorder motor and take up gear box essenbly failed on a System I recorder.

25X1D

# Approved For Release 2003/02/27 : CIA-RDP61-00763A0<del>001</del>00090058-2

DPD-2605-59 PAGE TWO

#### III. Photographic Equipment

A. During the period of 3 March 1959 through 31 March 1959, there were a total of thirty-four (34) missions reported flown using photographic equipment. Equipments malfunctioned on six (6) of these missions giving an overall affectiveness of 82.4%.

Equipment reliability for the above referenced period was:

|               | <u>A-1</u> | <u> </u> | B. Conf. | Inchers |
|---------------|------------|----------|----------|---------|
| Mission flown | 1          | 4<br>1   | 7        | 34<br>5 |
| Per Cent Rff. | 100%       | 75%      | 100%     | 85.3%   |

B. It should be noted that although tracker effectiveness was only 85.3%, the total number of missions flows with trackers were about five (5) times greater than the total flown with the "B" Conf.

SIGNED

25X1A

CFW:ms (20 April 1959)

Dist: 0 - Addressee

3 - MD/P

4 - Materiel, DPD 5 - Operations, DPD

-6 - RI/DPD

Chief, maverier section DPD-DD/P